
Location of T-16 and T-17



Change in soil conditions at T-16




Pipe discovered at T-16



Inside pipe discovered at T-16



Location of T-11



Product encountered in the trench outside the T-11 footprint



Location of T-21, T-22 and T-24



Northeast sidewall of T-21 excavation on April 20, 2010




White sticky material found in T-22 excavation on April 20, 2010



Black sticky material encountered in the T-24 excavation on April 20, 2010



Location of T-23



Concrete and wood encountered on top of the slab in the T-23 excavation



Slab located at the bottom of the T-23 excavation



Location of T-31



Top of UST in T-31



Location of T-35



## Foundation and slab in T-35



Pipes located between slab and foundation in T-35



Blackish material under eastern corner of concrete slab in T-35



Location of T-48



## Excavation sidewall in T-48



Location of T-54



Top of the T-54 structure cut open




Compartment inside the T-54 structure



Pipe entering/exiting the T-54 structure



Side of the T-54 structure



Green discoloration in the vicinity of T-54



Location of T-59



## Concrete and water in T-59 excavation



Location of T-60



## All of the red material found in T-60 excavation



Pipe found in T-60



Location where red material was found